Battle Damage Assessment and Repair, Maintainer

NSN: 5180-01-502-9507

System Description

Allows crew members to make field expedient repairs to return disabled equipment to an operational status by the use of short cuts, by-passes, fabrication, interchange, cannibalization, or jury-rigging. This kit includes: tire repair, tire patch electrical repair, fluid line repair, hull patch, fuel cell patch, hydraulic repair, belt replacement and radiator sealant.

This system is not currently in reset.

Reset Type

Reset Work (Field Level) - Work performed to correct equipment faults that are performed at the ORG/DS level; performed by unit level soldiers, augmented by contractor as required.

Reset Strategy

n/a

Reset Procedures

- Replace worn, broken, missing components IAW supply catalog.
- Reorder consumables IAW SC.

Reset Responsibility

Unit

Reset Location

This system is not currently in reset.

- Contact Information -

877.4.PMSKOT (877.476.7568) rock-pm-skot@conus.army.mil